

HISTORIC AMERICAN BUILDINGS SURVEY

MA-1000

INDEX TO PHOTOGRAPHS

Academy Building (Borden Block, Academy of Music)
58-114 South Main Street
Fall River
Bristol County
Massachusetts

Documentation: 7 sheets (1976, 1980, including title sheet elevations,
section, plans)
10 exterior photos (1979)
13 interior photos (1979)
17 data pages (1979)

William W. Owens, Jr., photographer September 16, 17, 18, 1979.

- MA-1000-1 WEST ELEVATION, THEATER ENTRANCE IN SOUTHERN PORTION
- MA-1000-2 NORTHWEST CORNER
- MA-1000-3 NORTH ELEVATION
- MA-1000-4 NORTHEAST CORNER
- MA-1000-5 EAST ELEVATION
- MA-1000-6 SOUTH ELEVATION (SIDE OF THEATER)
- MA-1000-7 DETAIL OF THEATER ENTRANCE, WEST ELEVATION
- MA-1000-8 DETAIL OF UPPER FLOORS, NORTHEAST CORNER
- MA-1000-9 CORNICE DETAIL, EAST ELEVATION
- MA-1000-10 DETAIL OF THREE-STORY WINDOWS, EAST ELEVATION
- MA-1000-11 MAIN STAIRCASE TO THEATER, VIEW LOOKING EAST FROM STREET ENTRANCE
- MA-1000-12 MAIN STAIRCASE AND STREET ENTRANCE, VIEW LOOKING WEST FROM
INTERIOR ENTRANCE
- MA-1000-13 STAIRCASE LEADING TO CENTRAL BALCONY, VIEW LOOKING EAST FROM
INTERIOR ENTRANCE
- MA-1000-14 STAIRCASE AND SOUTH WALL, VIEW FROM MIDDLE BALCONY

- MA-1000-15 PROSCENIUM AND STAGE, VIEW LOOKING NORTH FROM MIDDLE BALCONY
- MA-1000-16 VIEW OF THEATER FROM STAGE LOOKING SOUTH
- MA-1000-17 VIEW OF AUDITORIUM LOOKING EAST FROM MIDDLE BALCONY
- MA-1000-18 CHANDELIER IN AUDITORIUM, VIEW LOOKING NORTH FROM UPPER BALCONY
- MA-1000-19 FRESCOES AROUND CHANDELIER FROM ORCHESTRA, (FEMALE WITH DAGGER IS ON NORTH SIDE)
- MA-1000-20 BACKSTAGE AREA, VIEW LOOKING EAST
- MA-1000-21 DRESSING ROOM ON EAST SIDE OF THEATER, VIEW LOOKING NORTH
- MA-1000-22 LADIES LOUNGE, VIEW LOOKING SOUTH: STAIRS TO UPPER BALCONY ON LEFT
- MA-1000-23 TRUSSES, WEST SIDE OF CENTRAL ENCLOSURE VIEW LOOKING SOUTH